

Radonix CAM+

User Friendly and Easy to use Interface

Features

Controllable axes	Up to 3 Interpolate axes
CNC types	Routers, Engraving CNCs, Flame cut, Plasma, Laser cut, Water jet, Hot wire, Wire cut and Gluing CNC
Run direction	Forward and backward
Manual movement	Continues Jog / Step jog
Input file types	Standard G-Codes and DXF
Monitoring	3D display and signal for IOs
Safety command	Emergency and limit switches
Diagnostic	Daily and second by second report
Requirement computer	Pentium 5 and Upper
Requirement memory	At least 1GB
Platform	Microsoft framework 4.0
Operation system	Windows XP, Vista, 7, 8 and 10
Communication type	USB2.0